
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: <u>7/30/2009</u>
Test to be performed:  Smoke Dyed Water X	Ground Condition:  Dry ✓ Damp ☐ Wet ☐	Supervisor: <u>JAW</u>
Manhole_ID: S03WW_021MH	Test ID: <u>D1032-025010</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Water Level	
0			Manhole	S03WW_021MH
71.19999695			Dye Test Visible	@ TFA - downspout
73	03		Tap Factory Active	From 4025 Kathland
73.80000305			Dye Test Visible	@ TFA - cleanout
74			Manhole	S03WW_014MH
74			End of Survey	